



**US Army Corps  
of Engineers®**

Detroit District  
P.O. Box 1027  
Detroit, MI 48231-1027  
(313) 226-6797  
FAX - (313) 226-3519

# Notice to Navigation Interests

---

Notice No. L03-65

Date: 11 SEPTEMBER 2003

---

Waterway: LAKE HURON

Location: MICHIGAN

---

CELRE-OT-T


## CONDITION OF FEDERAL NAVIGATION CHANNEL PORT SANILAC HARBOR

1. After dredging surveys performed within the Federal navigation channel at Port Sanilac Harbor, Michigan during August 2003, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L03-65. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Home Page.

THOMAS H. MAGNESS  
Lieutenant Colonel, U.S. Army  
District Engineer

### Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2003.



The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: AUGUST 2003

0ptsan.bmp

All soundings are in feet and are referenced to Low Water Datum elevation 577.5 ft. above Mean Sea Level, IGLD 1985.



Shoals indicate least available depth below I.G.L.D.

PORT SANILAC HARBOR, MI

CONDITION OF CHANNEL

ISSUED: 11 SEPTEMBER 2003

U.S. Army Engineer District, Detroit